



Technical Data Sheet

WT-AR

Westech WT-AR is formulated as a solvent-based adhesive remover for industrial use.

DATA:

Color: Clear

Odor: Solvent like

Solvents: Cyclohexane/Acetone/Mineral Spirits

Flash Point: 0° F

Boiling Point: 200° F

Shelf life: Two Years

Optimum spray temperature: 60°F-80°F

Storage: Store away from heat

Flammable: Yes

Performance Features:

Removes most adhesives and is effective for many other cleaning operations.

Application:

Spray parts to be cleaned and wipe with cloth. Can be used to soak small parts. Repeat as necessary.

Safety Recommendations:

Vapors may be harmful to health. Nitrile gloves are suggested for use. Most solvents are transdermal and can pass through skin easily. Use only in well ventilated areas or utilize respiratory protection. The product MSDS should be read and understood before use. Eye protection is required. This product is flammable. Keep away from fire or flame. Keep away from children.

“DIRECTIONS: Shake can well BEFORE using. Wipe excess adhesive from surfaces with cloth dampened with AR.

For GUNJET cleaning–Attach AR to the applicator gun, ensuring a secure fit on the threaded valve. Do not over tighten. This will break the integral sealing valve. Always operate the can upside down and at arms length with the gun pointing away from the body. Carefully pull the trigger until cleaner extrudes from the gun tip. Release the trigger and let cleaning agent soak in for one to two minutes. Pull trigger, flush for at least 5 seconds and ensure the gun outlet tip is cleaned. Always dispense AR into suitable container. If necessary, repeat procedure two to three times until only clear cleaning agent appears from barrel. Place can upright, unscrew the can while pressing the trigger to ensure there is no build up of aerosol when disconnecting the gun applicator from can.

For SURFACE cleaning–Wipe excess uncured urethane foam and adhesives from tools and surfaces affected by overspray with a cloth dampened with Westech AR prior to curing.

Notice:

Westech Aerosol Corporation shall not be liable for any damage or loss arising from the use, purchase, or any inability to use this product, or for any indirect, incidental, special, or consequential damages. No warranties, expressed or implied are made including merchantability and/or fitness for a particular purpose. The user may return an allegedly defective sample to Westech for testing. If the sample proves defective, the remedies are either product replacement or reimbursement of purchase price for the defective product. No one has the authority to modify the limitations or obligations of this warranty.

Direct performance inquiries to: Westech Aerosol Corporation Quality Control, 5405 Constance Dr., Port Orchard, WA 98367, phone 360-674-2051, fax 360-674-2053

Westech Aerosol Corporation

5405 Constance Dr. SW

Port Orchard, WA 98367

Phone 360-674-2051 Fax 360-674-2053

<http://www.ok2spray.com/>